

STEP 3

 Franmar

TIP SHEET

D•HAZE®

HAZE REMOVER

Screen Ghost and Haze Remover

Made with Soybeans • 100% Biodegradable • Non-Toxic and Non-Caustic

Franmar's Haze Remover is one of the safest and most effective ghost and haze removers in the industry today! Unlike traditional caustic haze removers, **Franmar's Haze Remover** will not damage screen mesh no matter how long you leave it on. Good haze removal practices save screen printers money, with longer usability of screens.

Directions

- 1 Spray or pour a minimal amount onto screen haze/ghost image.
- 2 Scrub both sides of screen with dedicated Biggee™ pad or nylon brush.
- 3 Rinse screen clean with pressured water.

Usage Tips

- Use each time immediately after exposure or stencil removal so you don't need to set up the screen.
- Control amount by using a spray tube; washing frame pieces as Haze Remover will weaken the glue holding the mesh to the frame.
- Use Franmar's Screen Degreaser to remove any residue.

Chat with a live customer service rep (No phone menu maze!)

800-538-5069

7am - 5:30pm Mon - Thurs. Friday 7am - 5:00pm CT

or visit our website: www.franmar.com

 Franmar®

rev. 6/15/2015