



DATA SHEET



HR1000 Haze Remover (Ghost/Image Stain Remover)

American Eagle haze remover is sold strictly for use in the screen printing industry for effective removal of hazes and ghost images commonly left after stencil reclaiming. It negates the need for an additional solvent application. American Eagle may also be used to degrease and chemically abrade new or used aluminium frames prior to stretching.

WORKING INSTRUCTIONS & SAFE HANDLING

Operators must wear protective clothing including gloves, plastic apron and goggles. Avoid contact with skin and eyes. Avoid contact with strong acids and other chemicals. Use in an area with good ventilation. To remove Stains or Ghost Images:

1. Clean off all ink residue prior to stencil removal.
2. Remove stencil with recommended Fotec de-coating chemical product.
3. Apply a small amount of American Eagle haze remover to both sides of the wet mesh with a silicone brush, thoroughly covering the stained areas in a circular motion.
4. Leave to stand for 6-8 minutes. If left to stand for longer periods, American Eagle Haze Remover can damage the fibres of the mesh.
5. Rinse off residue with gently water spray.
6. Remove stain with high pressure stripper.

BIODEGRADABLE

Considered drain safe into all sewer treatment systems. For Industrial use only. Non-photochemically reactive.

CAUTION

Sodium Hydroxide. Always consult Data Sheet before using. Causes irritation to eyes skin and respiratory tract. Wash thoroughly after handling. Keep this container and product vapors away from heat, sparks and flame.

This product contains a corrosive material (Sodium Hydroxide). It is a blend of water based alkaline cleaners and solvent active detergents. A corrosive chemical can cause, when not washed with water, visible destruction of living tissue by chemical action at the site of contact. Per US department of Transportation, Appendix A to 40 CFR, Part 173 corrosives destroy or change the structure of the tissue at the site of contact following an exposure period of 4 hours. Always wear gloves, goggles and other protective apparel.

FIRST AID

In case of contact, immediately flush eyes with fresh water for at least 15 minutes. Contact a physician. Wash skin with soap and water. If inhaled, remove to fresh air. If breathing difficulty continues, give oxygen and obtain medical assistance.

IMPORTANT: The technical data herein is believed to be accurate. It is offered for your consideration, investigation and verification. Buyer assumes all risk of use, storage, and handling of the product. No warrant, express or implied is made, including but not limited to, implied warranties of merchant ability and fitness for a particular purpose. Nothing contained herein shall be construed as a license to operate under, or recommendation to infringe any patents.

**JONES PRINT TECHNOLOGY
38A CAPITAL LINK DRIVE
CAMPBELLFIELD, VIC, 3061**

**PH: +61 3 9357 5767
FX: +61 3 9357 5797**

E. sales@jonept.com.au